

#### **BUILDING DIRECTORY**

- A- KING & PRINCE HOTEL
- 3- OCEAN FRONT BUILDING

MAINTENANCE BUILDING

- OLEANDER BUILDING
- **E-** THE COTTAGE
- OGLETHORPE HOUSE
- **G-** WEDDING COTTAGE
- H- WYNN COTTAGE
- I- TABBY HOUSE

A T L A N T I C O C E A N

KING & PRINCE FACADE PROJECT

The Ling and Prince

R E S O R T

201 ARNOLD ROAD

ST. SIMONS ISLAND, GEORGIA

AS1



ARCHITECTURE — INTERIOR DESIGN — LAND PLANNING



#### **PROJECT NOTES PROJECT SPECIFICATIONS** EXTERIOR FINISH SCHEDULE **SPECIFICATIONS** PART 1 - MISCELLANEOUS 1. IF CONFLICT ARISES IN THE ENCLOSED DRAWINGS CONTACT ARCHITECT PRIOR TO PROCEEDING EXTERIOR PAINT 1.1 CONTRACTOR(S) MANUFACTURE: SHERWIN- WILLIAMS® 2. ALL WORK, MATERIALS, METHODS, ETC., SHALL CONFORM TO ALL GOVERNING BUILDING A. GENERAL CONTRACTOR SHALL BE LICENSED IN THE STATE OF GEORGIA. CODES, ORDINANCES, REGULATIONS AND AGENCIES PRIME COAT: LX02W0050 - LXN C&M PRIMER WH. APPLY @ 5.3 - 8.0 WET MILS B. SUB-CONTRACTORS SHALL BE LICENSED IN THE STATE OF GEORGIA AND CERTIFIED AS RECOMMENDED 2 COATS: LX14W0051 - LXN SELF-CLN SA EW. APPLY @ 5.0 - 7.0 WET MILS BY THE MANUFACTURER OF THE PRODUCT / SYSTEM BEING UTILIZED. 3. ALL NEW WORK TO MEET THE REQUIREMENTS OF 2018 INTERNATIONAL BUILDING CODE COLOR: SW 6140 MODERATE WHITE (VERIFY FINAL COLOR W/ OWNER) 1.2 INSURANCE 4. WHERE ANY CONFLICT EXISTS BETWEEN THESE DOCUMENTS & THE 2018 INTERNATIONAL FINISH: SATIN, (SEMI-GLOSS AT CAST STONE COLUMNS AT HOTEL BUILDING & OLEANDER BUILDING) BUILDING CODE, THE BUILDING CODE SHALL OVER RULE A. INSURANCE REQUIREMENTS OF CONTRACTOR; LOCATION: ALL EXTERIOR STUCCO, MASONRY, CAST STONE, CMU 5. ALL STEEL DOORS WITH EXISTING PAINT FINISH, SHALL RECEIVE NEW PAINT. VERIFY COLOR WORKER'S COMPENSATION NOTES: SUBSTRATE MUST BE THOROUGHLY CLEANED AND PREPPED PRIOR TO APPLYING PRIMER. CHALK, DIRT. a. AMOUNT MEETING STATUTORY LIMITS MANDATED BY STATE AND FEDERAL LAWS DEBRIS, AND LOOSE PAINT/MATERIAL NEEDS TO BE REMOVED PRIOR TO PRIMING. THIS CAN BE DONE BY PRESSURE REMOVE SHUTTERS BEFORE PAINTING. REINSTALL 2. BUILDER'S RISK WASHING AND SCRAPING. REMOVE ALL SURFACE CONTAMINATION BY WASHING WITH AN APPROPRIATE CLEANER, RINSE | a. AMOUNT REQUIRED TO COVER 100% OF ENTIRE PROJECT THOROUGHLY AND ALLOW TO DRY. EXISTING PEELED OR CHECKED PAINT SHOULD BE SCRAPED AND SANDED TO A 7. ALL WOOD SHUTTERS TO BE PREPPED & PAINTED. PROVIDE NEW SHUTTERS AS NEEDED SOUND SURFACE. GLOSSY SURFACES SHOULD BE SANDED DULL. WHERE WOOD SHUTTERS ARE BEYOND REPAIR. MATCH EXISTING 3. COMMERCIAL GENERAL LIABILITY a. AMOUNT MEETING STATUTORY LIMITS MANDATED BY STATE AND FEDERAL LAWS OR THE EXTERIOR PAINT 8. COMPOSITE / VINYL SHUTTERS TO BE REMOVED, INSPECTED BY OWNER, PAINTED & FOLLOWING; WHICHEVER IS GREATER; REINSTALLED BY CONTRACTOR MANUFACTURE: SHERWIN- WILLIAMS® 1) \$ 1,000,000 EACH OCCURRENCE PRIMER: Y24W08020 - EXTERIOR OIL-BASED WOOD PRIMER. APPLY @ 4.0 - 5.0 WET MILS 2) \$ 2,000,000 GENERAL AGGREGATE 4. PREP & PAINT WOOD WINDOWS. REPAIR DETERIORATED WOOD AS NEEDED. PROVIDE NEW 3) \$1,000,000 PERSONAL AND ADVERTISING INJURY GLAZING AS NEEDED 2 COATS: K48W01951 - EMRLD RNRF EXSA EW. APPLY & 5.3 - 6.4 WET MILS 4) \$ 2,000,000 PRODUCTS-COMPLETED OPERATIONS AGGREGATE COLOR: SW 6140 MODERATE WHITE (VERIFY FINAL COLOR W/ OWNER) (VERIFY SHUTTER COLOR) 5. DO NOT PAINT CLAD WINDOWS 4. COMPREHENSIVE AUTOMOBILE LIABILITY a. AMOUNT MEETING STATUTORY LIMITS MANDATED BY STATE AND FEDERAL LAWS OR THE 7. DO NOT PAINT COPPER DRIP EDGE OR COPPER PARAPET CAP FOLLOWING; WHICHEVER IS GREATER; LOCATION: ALL WOOD TRIM, SOFFIT, FASCIA & WOOD BALCONY & PORCH CEILINGS. 'HARDIE' PANEL - BOARD & BATTEN 1) \$ 1,000,000 COMBINED SINGLE LIMIT BODILY INJURY AND PROPERTY DAMAGE 6. RESEAL ALL PARAPET CAP JOINTS, REMOVE EXISTING SEALANT, CLEAN & RESEAL AS NEEDED NOTE: REPAIR CRACKS, VOIDS, AND OTHER HOLES WITH AN APPROPRIATE PATCHING COMPOUND 2) \$1,000,000 BODILY INJURY EACH PERSON NOTE: SUBSTRATE MUST BE THOROUGHLY CLEANED AND PREPPED PRIOR TO APPLYING PRIMER. REMOVE ALL 3) \$ 1,000,000 BODILY INJURY EACH OCCURRENCE SURFACE CONTAMINATION SUCH AS OIL, GREASE, LOOSE PAINT, MILL SCALE DIRT, RUST, MOLD, MILDEW AND SEALERS 4) \$ 1,000,000 PROPERTY DAMAGE EACH OCCURRENCE 8. PREP & PAINT ALL EXPOSED STEEL LINTELS AT BRICK VENEER. SEE SCHEDULE FOR PAINT. MUST BE REMOVED TO ASSURE SOUND BONDING TO THE TIGHTLY ADHERING OLD PAINT. GLOSSY SURFACES OF OLD ANY STEEL LINTELS DEGRADED PAST REPAIR SHALL BE REVIEWED ON SITE WITH OWNER PAINT FILMS MUST BE CLEAN AND DULL BEFORE REPAINTING. THOROUGHLY WASH WITH AN ABRASIVE CLEANSER, OR 1.3 RETAINAGE AND REPLACED, TO MATCH EXISTING. WASH THOROUGHLY AND DULL BY SANDING. PATCH ALL NAIL HOLES AND IMPERFECTIONS WITH WOOD FILLER OR PUTTY A. THE OWNER WILL RETAIN 5% OF EACH REQUEST. UNLESS OTHERWISE NEGOTIATED. AND SAND SMOOTH. CAULK SHOULD BE APPLIED AFTER PRIMING 9. ALL CONTROL JOINTS & EXPANSION JOINTS WITH EXISTING SEALANT, SHALL BE CLEANED AND RE-SEALED. SEE SPECIFICATIONS FOR NEW SEALANT TYPE. EJ-1 EXTERIOR PAINT MANUFACTURE: SHERWIN- WILLIAMS® 10. PROVIDE NEW SEALANT AT ALL WINDOWS & DOORS. REMOVE EXISTING SEALANT AS PART 2 - GENERAL REQUIREMENTS NEEDED PRIME COAT: B66W01310 - PI PROCRYL PR OF W. APPLY @ 5.0 - 10.0 WET MILS 2.1 SUMMARY 2 COATS: B53W05151 - PI WB ALK UR SG EW. APPLY @ 4.0 - 5.0 WET MILS 11. PATCH & SEAL ANY CRACKS IN STUCCO FINISHES, MATCH EXISTING TEXTURE. A. USE OF PREMISES COLOR: MATCH EXISTING (BLACK) (WHITE) VERIFY FINAL COLOR W OWNER. (BROWN - AT OGLETHORPE HOUSE DOOR) 12. REPLACE DEGRADED STUCCO CORNER BEAD AS NEEDED AND REPAIR ASSOCIATED STUCCO 1. OWNER OCCUPANCY: THE OWNER AND GUESTS WILL OCCUPY THE FACILITY AND GROUNDS DURING CONSTRUCTION. LOCATION: METAL HANDRAILS, METAL DOORS & FRAMES B. WORK RESTRICTIONS: 13. PROTECT ALL SURFACES NOT RECEIVING PAINT. DAILY ON-SITE WORK HOURS; NOTES: ALL SURFACE RUST MUST BE REMOVED PRIOR TO PRIMING. SURFACE MUST BE CLEAN DRY AND IN SOUND CONDITION. REMOVE ALL LOOSE MILL SCALE, LOOSE RUST AND OTHER DETRIMENTAL FOREIGN MATERIAL TO ENSURE NOTIFY OWNER OF ANY DEFICIENCIES DISCOVERED DURING PREP WORK. MONDAY - FRIDAY: 8:00 AM - 6:00 PM ADEQUATE ADHESION BY HAND CHIPPING, SCRAPING, SANDING, AND WIRE BRUSHING. BEFORE TOOL CLEANING, SATURDAY: 8:00 AM - 6:00 PM 15. COORDINATE REPAIR WORK WITH OTHER TRADES AS NEEDED. REMOVE SOLUBLE RESIDUES, AND SALTS. NO WORK ALLOWED EXTERIOR PAINT 16. RESEAL & PATCH CRACKED AREAS OF MODIFIED BITUMEN ROOF AT HOTEL BUILDING, SEE 2. THE OWNER RESERVES THE RIGHT TO STOP WORK IN SPECIFIC AREAS DUE TO EVENTS TAKING 'BECI CONDITION ASSET EVALUATION REPORT' 2025 MANUFACTURE: SHERWIN- WILLIAMS® PLACE AT THE FACILITY. PREPRIME: B58T00101 - MACROPOXY 920 PREPRIME RUST PENETRATING EPOXY PRE-PRIMER TRANSPARENT PART-A. 17. SCOPE OF REPAIR WORK NOT LIMITED TO EXTERIOR LEGEND MARKS, FIELD VERIFY ALL B58V10 HARDNER. 3:1 MIX RATIO A to B. APPLY @ 1.5 - 2.0 WET MILS 3. NONSMOKING PROPERTY: SMOKING IS NOT PERMITTED WITHIN ANY BUILDING OR ON THE LOCATIONS. PROPERTY UNLESS IN DESIGNATED AREAS. PRIME COAT: B58W00610 - MACROPOXY 646 FAST CURE EPOXY PART A MILL WHITE. B58V600 HARDNER. 1:1 MIX RATIO A 18. ANY NEW WOOD SHALL BE K.D.A.T. (KILN DRIED AFTER TREATMENT P.T. (PRESSURE TREATED) TO B. APPLY @ 7.0 - 13.5 WET MILS 4. DAILY AND WEEKLY CLEANUP: THE CONTRACTOR SHALL MAINTAIN A CLEAN WORK AREA. DAILY APPEARANCE GRADE - SUITABLE FOR TRIM. FINISH COAT: B80W00551 - SHRLXN800 SG XWH A. B80W500 STANDARD TEMP HARDNER. 4:1 MIX RATIO A TO B @ 5.0 - 7.0 CLEAN-UP OF WORK AREAS IS REQUIRED. WEEKLY CLEAN-UP OF THE ENTIRE PROPERTY IS REQUIRED. 19. REPAIR DAMAGED TRIM AS REQUIRED, USE ABATRON WOOD EPOX AND OR ABATRON LIQUIDWOOD. FOLLOW MANUFACTURERS RECOMMENDED PROCESS & PROCEDURES FOR COLOR: SW 6140 MODERATE WHITE (VERIFY FINAL COLOR W/ OWNER) INSTALLATION. SAND FOR SEAMLESS TRANSITION. PRIME FOR NEW PAINT. FINISH: SEMI-GLOSS A. PROVIDE SUBMITTALS (PRODUCT DATA, SAMPLES, AND MOCK-UPS) FOR ALL SPECIFIED MATERIALS AND 20. ANY NEW FASTENERS SHALL BE STAINLESS STEEL PRODUCTS. SUBMITTALS SHALL BE SUBMITTED TO THE ARCHITECT FOR REVIEW AND APPROVAL PRIOR LOCATION: STEEL LINTEL AT WINDOWS, ANCHOR BOLTS & PIPE COLUMNS TO WORK TAKING PLACE. NOTES: POWER TOOL CLEANING REMOVES ALL LOOSE MILL SCALE, LOOSE RUST, AND OTHER DETRIMENTAL FOREIGN 21. REMOVE ANY ABANDONED CABLE & WIRING THROUGHOUT, INCLUDING MISC. BRACKETS MATTER. IT IS NOT INTENDED THAT ADHERENT MILL SCALE, RUST, AND PAINT BE REMOVED BY THIS PROCESS. MIL 2.3 PROCEDURES FOR HISTORIC TREATMENT SCALE, RUST, AND PAINT ARE CONSIDERED ADHERENT IF THEY CANNOT BE REMOVED BY LIFTING WITH A DULL PUTTY 22. COVER AND PROTECT FROM DAMAGE ALL EXTERIOR PARTS OF THE BUILDING NOT A. PROTECT ADJACENT HISTORIC MATERIALS AGAINST DAMAGE AND SOILING DURING WORK. KNIFE. BEFORE POWER TOOL CLEANING, REMOVE VISIBLE OIL, GREASE, SOLUBLE WELDING RESIDUES, AND SALTS BY SCHEDULED FOR REPAIR. THE METHODS OUTLINED IN SSPC-SP1. FOR COMPLETE INSTRUCTIONS, REFER TO STEEL STRUCTURES PAINT COUNCIL SURFACE PREPARATION SPECIFICATION NO.3. 2.4 QUALITY REQUIREMENTS 23. ALL SURFACE CONTAMINATION SUCH AS LOOSE PAINT, DIRT, FOREIGN MATTER, MOLD, EXTERIOR PAINT MILDEW, AND VEGETATION, MUST BE REMOVED TO ASSURE SOUND BONDING TO THE OLD A. SPECIAL TESTS AND INSPECTIONS: OWNER WILL ENGAGE A QUALIFIED TESTING AGENCY TO CONDUCT PAINT. WASH THOROUGHLY AND DULL BY SANDING. SPOT PRIME ANY BARE AREAS WITH SPECIAL TESTS AND INSPECTIONS REQUIRED BY AUTHORITIES HAVING JURISDICTION AS THE MANUFACTURE: SHERWIN- WILLIAMS® RESPONSIBILITY OF OWNER PRIMER: Y24W08020 - EXTERIOR OIL-BASED WOOD PRIMER. APPLY @ 4.0 - 5.0 WET MILS 24. REPOINT BRICK MORTAR JOINTS, AS NEEDED AT DETERIORATED LOCATIONS DISCOVERED 2.5 TEMPORARY UTILITIES & SAFETY: 2 COATS: K48W01951 - EMRLD RNRF EXSA EW. APPLY & 5.3 - 6.4 WET MILS DURING PAINT PREP A. TEMPORARY UTILITIES: THE CONTRACTOR WILL BE ALLOWED TO USE THE UTILITIES ALREADY ON SITE COLOR: (VERIFY FINAL COLOR W/ OWNER) (IE. ELECTRICAL AND WATER) AT NO COST, UNLESS NOTABLE OVERAGES IN USE ARE INCURRED. THE 25. REPLACE SEALANT AT TOP EDGE OF TERMINATION STRIP, AT THE INSIDE OF PARAPET WALLS. CONTRACTOR SHALL PROVIDE TEMPORARY TOILET FACILITY (PORTABLE TOILET) FOR THE DURATION FINISH: SATIN OF THE PROJECT. 26. REPLACE SEALANT AT TOP EDGE OF SIDE WALL FLASHING, TYPICAL. LOCATION: ALL WOOD SHUTTERS, ALL COMPOSITE / VINYL SHUTTERS B. SAFETY: THE CONTRACTOR SHALL PROVIDE ONE 5 LB. 2A:10B:C (OR LARGER) PORTABLE FIRE NOTE: REPAIR CRACKS, VOIDS, AND OTHER HOLES WITH AN APPROPRIATE PATCHING COMPOUND 27. CONTRACTOR TO VERIFY THE EXISTENCE OF LED BASED PAINTS ON THE PROJECT. IF LED EXTINGUISHER IN ALL AREAS OF WORK READILY AVAILABLE FOR USE DURING THE COURSE OF WORK. BASED PAINTS ARE SUSPECTED ON THE PROJECT, ALL REMOVAL MUST BE DONE IN PORTABLE FIRE EXTINGUISHERS SHALL BE PRESENT DURING ALL OPERATIONS INVOLVING ANY METAL NOTE: SUBSTRATE MUST BE THOROUGHLY CLEANED AND PREPPED PRIOR TO APPLYING PRIMER. REMOVE ALL WORKING THAT MAY RESULT IN SPARKS OR HOT SLAG BEING FORMED. (I.E. GRINDING, WELDING, ACCORDANCE WITH THE EPA RENOVATION, REPAIR AND PAINTING AND ALL APPLICABLE STATE SURFACE CONTAMINATION SUCH AS OIL, GREASE, LOOSE PAINT, MILL SCALE DIRT, RUST, MOLD, MILDEW, MORTAR, CUTTING, ETC.) & LOCAL REGULATIONS. EFFLORESCENCE AND SEALERS MUST BE REMOVED TO ASSURE SOUND BONDING TO THE TIGHTLY ADHERING OLD PAINT. GLOSSY SURFACES OF OLD PAINT FILMS MUST BE CLEAN AND DULL BEFORE REPAINTING. THOROUGHLY WASH 28. ALL PAINTS & SEALANTS, SHALL BE INSTALLED PER MANUFACTURERS INSTRUCTIONS. 2.6 CUTTING AND PATCHING WITH AN ABRASIVE CLEANSER, OR WASH THOROUGHLY AND DULL BY SANDING. PATCH ALL NAIL HOLES AND INCLUDING REQUIRED PREP WORK IMPERFECTIONS WITH WOOD FILLER OR PUTTY AND SAND SMOOTH. CAULK SHOULD BE APPLIED AFTER PRIMING A. IN-PLACE MATERIALS: USE MATERIALS IDENTICAL TO IN-PLACE MATERIALS. FOR EXPOSED SURFACES, USE MATERIALS THAT VISUALLY MATCH IN-PLACE ADJACENT SURFACES TO THE FULLEST EXTENT EXTERIOR STAIN 29. AT CLAD WINDOWS, IN HISTORIC ROOMS & OCEAN FRONT ROOMS, LOCATED IN THE HOTEL POSSIBLE. BUILDING - REMOVE LOOSE CLADDING PIECES, RE-ATTACH WITH ADHESIVE AND PROVIDE MANUFACTURE: MINWAX® SEALANT AS NEEDED TO ACHIEVE A WATER TIGHT SEAL 2.7 SELECTIVE DEMOLITION STAIN COAT: 066060000 MINWAX GEL STAIN WALNUT (VERIFY FINAL STAIN SELECTION W OWNER) A. COMPLY WITH ALL REGULATORY AGENCIES GOVERNING DEMOLITION, HAULING, AND DISPOSAL OF 3 COATS: 013210000 - MINWAX INDOOR/OUTDOOR HELMSMAN SPAR URETHANE VARNISH SEMI-GLOSS CLEAR. APPLY @ DEMOLITION WASTE MATERIAL. 2.0 - 3.0 WET MILS B. COMPLETELY REMOVE AND LEGALLY DISPOSE OF BUILDINGS AND SITE IMPROVEMENTS AS IDENTIFIED ( S-1) FINISH: SEMI-GLOSS ON THE DEMOLITION PLANS TO INCLUDE SUB-GRADE STRUCTURES AND UTILITIES. COLOR: AS SELECTED. (VERIFY W OWNER) 2.8 LANDSCAPE LOCATION: ALL EXISTING STAINED DOORS A. LANDSCAPE SHALL BE PROTECTED FROM DAMAGE AT ALL TIMES DURING WORK. THE GENERAL NOTES: SURFACE MUST BE CLEAN DRY AND IN SOUND CONDITION. REMOVE ALL LOOSE COATINGS AND OTHER CONTRACTOR SHALL REPLACE ANY DAMAGED LANDSCAPING WITH SIMILAR SIZED LANDSCAPING AND FOREIGN MATERIAL TO ENSURE ADEQUATE ADHESION BY HAND CHIPPING, SCRAPING, SANDING, AND WIRE BRUSHING. OF THE SAME SPECIES. BEFORE TOOL CLEANING, REMOVE SOLUBLE RESIDUES, AND SALTS. EXTERIOR STAIN MANUFACTURE: SHERWIN- WILLIAMS® FIRST COAT: A19T00554 - WDSCPS RR SC UD. APPLY @ 4.5 WET MILS

SYMBOL	SPECIFICATIONS
	STUCCO - SMALL PATCH COMPOUNDS
SP-1	MANUFACTURE: SHERWIN- WILLIAMS®
	STUCCO: WL70010GT - MASONRY PATCH AND SEAL 11 oz. TEXTURED
	LOCATION: EXTERIOR STUCCO CRACKS 1/16" TO 3/8"
	NOTES: INSTALL PER MANUFACTURERS INSTRUCTIONS  NOTES: BRIDGE OVER VOIDS AND SMALL CRACKS UP TO 1/16" WIDE USING CONCRETE & MASONRY PATCH. TO ENSURE THAT THE REPAIRED AREA BLENDS INTO THE SURROUNDING SURFACE, PROVIDE SUFFICIENT CREST OVER THE OPENING TO ALLOW FOR SHRINKAGE. THE PATCH MUST BE FEATHERED TO ZERO AT THE EDGES USING A BRUSH, KNIFE, OR TROWEL. DO NOT APPLY MORE THAN 1/4" IN DEPTH IN ONE APPLICATION
	NOTES: CRACKS AND VOIDS BETWEEN 1/16" AND 3/8" WIDE SHOULD BE OPENED TO A SOUND SURFACE. TO ENSURE THAT THE REPAIRED AREA BLENDS INTO THE SURROUNDING SURFACE, PROVIDE SUFFICIENT CREST OVER THE OPENING TO ALLOW FOR SHRINKAGE. THE PATCH MUST BE FEATHERED TO ZERO AT THE EDGES USING A BRUSH, KNIFE, OR TROWEL, TO PREVENT THE REPAIRED OPENING FROM TELEGRAPHING THROUGH THE SUBSEQUENT FINISHES. DO NOT APPLY MORE THAN 1/4" IN DEPTH IN ONE APPLICATION. THE DEPTH OF THE OPENING SHOULD BE 1/2 THE WIDTH OF THE OPENING, WITH A MAXIMUM DEPTH OF 1/2". IN DEEP OPENINGS, THE DEPTH OF THE PATCH SHOULD BE CONTROLLED WITH A CLOSED CELL, "NON-GASSING" TYPE BACKER ROD. IF THE OPENING IS 1/4" OR GREATER, FOR MAXIMUM PERFORMANCE, PREVENT 3 POINT ADHESION WITH BACKER RODS OR BOND BREAKER TAPE.
	STUCCO - SMALL PATCH COMPOUNDS
	MANUFACTURE: RAPID SET®
	STUCCO: 09784711 - RAPID SET STUCCO NO. 10 TEXTURED
SP-2	LOCATION: EXTERIOR STUCCO CRACKS 1/8" TO 1"
	NOTE: INSTALL PER MANUFACTURES INSTRUCTIONS NOTE: APPLICATION SURFACE MUST BE CLEAN, SOUND AND FREE FROM ANY MATERIALS THAT MAY INHIBIT BOND, SUCH AS OIL, CURING COMPOUND, ACID, DIRT AND LOOSE DEBRIS. ROUGHEN SURFACE AND REMOVE ALL UNSOUND MATERIAL. OPEN CRACKS TO MINIMUM $\frac{1}{4}$ " WIDTH. IN HOT, DRY, OR WINDY ENVIRONMENTS, PRE-WETTING OF THE SURFACE TO BE PATCHED MAY BE NECESSARY.
	STUCCO - FULL REPAIR
	MANUFACTURE: TOTAL WALL & SHERWIN- WILLIAMS®
	STUCCO: 09450214 - 'TOTAL WALL' JRNYMN SHTBLST MB
	PRIME COAT: LX02W0050 - LXN C&M PRIMER WH. APPLY @ 5.3 - 8.0 WET MILS
SR-1	2 COATS: LX14W0051 - LXN SELF-CLN SA EW. APPLY @ 5.0 - 7.0 WET MILS
	COLOR: WHITE (VERIFY FINAL COLOR W/ OWNER)
	FINISH: SATIN  LOCATION: FULL REPAIR STUCCO
	NOTES: APPLICATION SURFACE MUST BE CLEAN, SOUND AND FREE FROM ANY MATERIALS THAT MAY INHIBIT BOND, SUCH AS OIL, CURING COMPOUND, ACID, DIRT AND LOOSE DEBRIS. ROUGHEN SURFACE AND REMOVE ALL UNSOUND MATERIAL
	EXPANSION JOINTS
	MANUFACTURE: SHERWIN- WILLIAMS®
EJ-1	SEALANT: LX21S0043 - SU 1S WHITE 20 OZ
	COLOR: WHITE  NOTES: JOINTS LARGER THAN ½" SHOULD BE FILLED WITHIN ½" OF THE SURFACE WITH POLYURETHANE ROD OR CLOSED CELL URETHANE FOAM
	NOTES: INSTALL PER MANUFACTURES DIRECTIONS
	WINDOW & DOOR SEALANT
	MANUFACTURE: SHERWIN- WILLIAMS®
	SEALANT: WL001360A - CAULK - SHER-MAX ULTRA URETHANIZED ELASTOMERIC SEALANT 11 OZ.
	COLOR: WHITE
SL-1	NOTES: JOINTS MORE THAN $\frac{1}{2}$ " SHOULD BE FILLED WITHIN $\frac{1}{2}$ " OF THE SURFACE WITH POLYURETHANE ROD OR CLOSED CELL URETHANE FOAM.
	NOTE: INSTALL PER MANUFACTURERS INSTRUCTIONS
	NOTES: SURFACES TO BE CAULKED/SEALED MUST BE CLEAN, DRY AND FREE FROM OILS, LOOSE MORTAR, LAITANCE, FORM RELEASE AGENTS, OLD CAULKING, OLD PAINT OR OTHER CONTAMINANTS. ALLOW NEW CONCRETE TO CURE FOR 30 DAYS BEFORE CAULKING. TOOL CAULK WITH APPROPRIATE TOOL TO ENSURE FIRM, FULL CONTACT WITH THE SURFACE OR THE JOINT. IF NECESSARY, SMOOTH THE SURFACE WITH WET FINGER OR SPATULA AND WIPE OFF THE EXCESS WITH A WATER-DAMPENED RAG.
	FLASHING SEALANT - SIDE WALL & TERMINATION STRIPS
	MANUFACTURE: UNIFLEX
	SEALANT: KST058300 - UF MS HYB RS-WHITE
SL-2	COLOR: WHITE
	NOTES: INSTALL PER MANUFACTURERS INSTRUCTIONS  NOTES: SURFACES TO BE CAULKED/SEALED MUST BE CLEAN, DRY AND FREE FROM OILS, LOOSE MORTAR, LAITANCE, FORM RELEASE AGENTS, OLD CAULKING, OLD PAINT OR OTHER CONTAMINANTS. ALLOW NEW
	CONCRETE TO CURE FOR 30 DAYS BEFORE CAULKING  SEALANT - AT PARAPET CAP
	MANUFACTURE: UNIFLEX
	SEALANT: KST058350 - UF MS HYB RS-CLEAR
SL-3	COLOR: CLEAR
	NOTES: INSTALL PER MANUFACTURERS INSTRUCTIONS
	NOTES: SURFACES TO BE CAULKED/SEALED MUST BE CLEAN, DRY AND FREE FROM OILS, LOOSE MORTAR, LAITANCE, FORM RELEASE AGENTS, OLD CAULKING, OLD PAINT OR OTHER CONTAMINANTS. ALLOW NEW CONCRETE TO CURE FOR 30 DAYS BEFORE CAULKING

MATERIAL & SYSTEMS SCHEDULE

CONTACT: SHERWIN WILLIAMS MR. LOGAN DULL LOGAN.G.DULL@SHERWIN.COM C:912.270.5210 O:912.265.3695

SECOND COAT: A19T00554 - WDSCPS RR SC UD. APPLY @ 4.5 WET MILS

LOCATION: ALL EXISTING STAINED PORCH CEILINGS AT HOTEL BUILDING

MATTER. REMOVE SURFACE STAINS, DIRT AND FAILED OXIDIZED STAINS OR FINISHES.

NOTES: ALL SURFACES MUST BE CLEAN, DRY AND FREE FROM DIRT, MILDEW STAINS, DUST AND OTHER FOREIGN

COLOR: AS SELECTED. (VERIFY W OWNER)

### KING & PRINCE FACADE PROJECT



2519	11-12-25
$C \cap$	
G.0	
	-









#### **SCOPE OUTLINE** (KING & PRINCE MAIN BUILDING)

- 1. PREP & PAINT ALL STUCCO, REPAIR ALL CRACKS, SP-1, SP-2, OR SR-1 VERIFY
- PREP & PAINT ALL BRICK, REPOINT MORTAR JOINTS, AS NEEDED AT DETERIORATED LOCATIONS.
- PREP & PAINT ALL RAILINGS & HANDRAILS.
  REMOVE SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1.
- 5. REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, PREOVIDE NEW SEALNT EJ-1 OR SL-1 VERIFY.
- PREP & PAINT ALL FASCIA & SOFFIT.
   PREP & PAINT ALL PORCH & BALCONY CEILINGS.
- 8. PREP & PAINT STEEL DOORS.

ACHIEVE A WATER TIGHT SEAL

- 9. PREP & STAIN ENTRY DOORS, AS SPECIFIED.
- 10. INSPECT ROOF TILES & REPLACE BROKEN / MISSING TILES.11. REMOVE SEALANT AT ALL SIDE-WALL ROOF FLASHING LOCATIONS, PROVIDE NEW SEALANT SL-2.
- 12. PREP AND RE-PATCH MODIFIED BITMUEN ROOF AS NEEDED AT CRAZING & DETERIORATED JUNCTIONS.
- REMOVE SEALANT AT ALL PARAPET CAP JOINTS, PROVIDE NEW SEALANT SL-3.
   AT CLAD WINDOWS, IN HISTORIC ROOMS & OCEAN FRONT ROOMS, LOCATED IN THE HOTEL BUILDING -REMOVE LOOSE CLADDING PIECES, RE-ATTACH WITH ADHESIVE AND PROVIDE SEALANT AS NEEDED TO

#### **GENERAL NOTES**

- 1. CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS
- 2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE
- 3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT








NORTHWEST ELEVATION

# KING & PRINCE FACADE PROJECT



2519	11-12-25
AI	


ARCHITECTS	ARCHITE 1804-A FRE	LE MORELAN CTS, P.C. DERICA ROAD SLAND, GA 31522 WWW.URarch.com
ARCHITECTURE —	— INTERIOR DESIGN—	LAND PLANNING





N.T.S.


DETAIL



N.T.S.




N.T.S.





PROVIDE NEW COPPER PARAPET CAP. SEE 5/A1.3. TYPICAL AT SOLARIUM ROOF

N.T.S.



PREP & PAINT STEEL COLUMNS & —— STEEL BASE PLATES / ANCHOR BOLTS, AT STAIR. SEE 2/A1.2





### **GENERAL NOTES**

- 1. CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS
- 2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE
- 3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT



### NORTHEAST ELEVATION

#### **SCOPE OUTLINE** (KING & PRINCE MAIN BUILDING)

- PREP & PAINT ALL STUCCO, REPAIR ALL CRACKS, SP-1, SP-2, OR SR-1 VERIFY PREP & PAINT ALL BRICK, REPOINT MORTAR JOINTS, AS NEEDED AT DETERIORATED LOCATIONS.
- PREP & PAINT ALL RAILINGS & HANDRAILS. 4. REMOVE SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1.
- REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, PREOVIDE NEW SEALNT EJ-1 OR SL-1 VERIFY.
- 6. PREP & PAINT ALL FASCIA & SOFFIT. 7. PREP & PAINT ALL PORCH & BALCONY CEILINGS.
- 8. PREP & PAINT STEEL DOORS.
- 9. PREP & STAIN ENTRY DOORS, AS SPECIFIED. 10. INSPECT ROOF TILES & REPLACE BROKEN / MISSING TILES.
- 11. REMOVE SEALANT AT ALL SIDE-WALL ROOF FLASHING LOCATIONS, PROVIDE NEW SEALANT SL-2.
- 12. PREP AND RE-PATCH MODIFIED BITMUEN ROOF AS NEEDED AT CRAZING & DETERIORATED JUNCTIONS. 13. REMOVE SEALANT AT ALL PARAPET CAP JOINTS, PROVIDE NEW SEALANT SL-3.
- 14. AT CLAD WINDOWS, IN HISTORIC ROOMS & OCEAN FRONT ROOMS, LOCATED IN THE HOTEL BUILDING -REMOVE LOOSE CLADDING PIECES, RE-ATTACH WITH ADHESIVE AND PROVIDE SEALANT AS NEEDED TO ACHIEVE A WATER TIGHT SEAL

# KING & PRINCE

FACADE PROJECT


ST. SIMONS ISLAND, GEORGIA



2519 11-12-25







**GENERAL NOTES** 

- 3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT

#### **SCOPE OUTLINE** (KING & PRINCE MAIN BUILDING)

- PREP & PAINT ALL STUCCO, REPAIR ALL CRACKS, SP-1, SP-2, OR SR-1 VERIFY
- PREP & PAINT ALL BRICK, REPOINT MORTAR JOINTS, AS NEEDED AT DETERIORATED LOCATIONS.
- PREP & PAINT ALL RAILINGS & HANDRAILS. 4. REMOVE SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1.
- REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, PREOVIDE NEW SEALNT EJ-1 OR SL-1 VERIFY.
- PREP & PAINT ALL FASCIA & SOFFIT.
- 7. PREP & PAINT ALL PORCH & BALCONY CEILINGS.
- 8. PREP & PAINT STEEL DOORS. 9. PREP & STAIN ENTRY DOORS, AS SPECIFIED.
- 10. INSPECT ROOF TILES & REPLACE BROKEN / MISSING TILES.
- 11. REMOVE SEALANT AT ALL SIDE-WALL ROOF FLASHING LOCATIONS, PROVIDE NEW SEALANT SL-2. 12. PREP AND RE-PATCH MODIFIED BITMUEN ROOF AS NEEDED AT CRAZING & DETERIORATED JUNCTIONS.
- 13. REMOVE SEALANT AT ALL PARAPET CAP JOINTS, PROVIDE NEW SEALANT SL-3.

14. AT CLAD WINDOWS, IN HISTORIC ROOMS & OCEAN FRONT ROOMS, LOCATED IN THE HOTEL BUILDING -REMOVE LOOSE CLADDING PIECES, RE-ATTACH WITH ADHESIVE AND PROVIDE SEALANT AS NEEDED TO ACHIEVE A WATER TIGHT SEAL



-PROVIDE NEW COPPER PARAPET CAP. SEE 5/A1.3. TYPICAL AT

PROVIDE SEALANT AT ALL

AT CRACKING BRICK,

AT ALL WINDOWS &

PARAPET CAP, PROVIDE

SEALANT SL-3

P.T. SHAPED 2X

SLIP JOINTS AS NEEDED.

**DETAIL** A1.3

N.T.S.

NEW TPO UNDER -PARAPET CAP



N.T.S.

\ A1.3

SOUTHEAST ELEVATION

KING & PRINCE FACADE PROJECT



A1.3 201 ARNOLD ROAD ST. SIMONS ISLAND, GEORGIA

2519

11-12-25











NORTHEAST COURTYARD ELEVATION



SOUTHWEST COURTYARD ELEVATION

#### **GENERAL NOTES**

- 1. CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS
- 2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE
- 3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT

#### **SCOPE OUTLINE** (KING & PRINCE MAIN BUILDING)

AT COURTYARD

- PREP & PAINT ALL STUCCO, REPAIR ALL CRACKS, SP-1, SP-2, OR SR-1 VERIFY
- PREP & PAINT ALL BRICK, REPOINT MORTAR JOINTS, AS NEEDED AT DETERIORATED LOCATIONS.
- PREP & PAINT ALL RAILINGS & HANDRAILS.
  REMOVE SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1.
- REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, PREOVIDE NEW SEALNT EJ-1 OR SL-1 VERIFY. PREP & PAINT ALL FASCIA & SOFFIT.
- PREP & PAINT ALL PORCH & BALCONY CEILINGS.
- 8. PREP & PAINT STEEL DOORS.9. PREP & STAIN ENTRY DOORS, AS SPECIFIED.
- 10. INSPECT ROOF TILES & REPLACE BROKEN / MISSING TILES.
- 11. REMOVE SEALANT AT ALL SIDE-WALL ROOF FLASHING LOCATIONS, PROVIDE NEW SEALANT SL-2.
- 12. PREP AND RE-PATCH MODIFIED BITMUEN ROOF AS NEEDED AT CRAZING & DETERIORATED JUNCTIONS.
- 13. REMOVE SEALANT AT ALL PARAPET CAP JOINTS, PROVIDE NEW SEALANT SL-3.
  14. AT CLAD WINDOWS, IN HISTORIC ROOMS & OCEAN FRONT ROOMS, LOCATED IN THE HOTEL BUILDING -REMOVE LOOSE CLADDING PIECES, RE-ATTACH WITH ADHESIVE AND PROVIDE SEALANT AS NEEDED TO ACHIEVE A WATER TIGHT SEAL

# KING & PRINCE FACADE PROJECT



2519	11-12-25
A 1 1	
A1.4	





### NORTHWEST ELEVATION




SOUTHEAST ELEVATION




### SOUTH WEST ELEVATION









SCOPE OUTLINE (OCEANFRONT BUILDING)

PREP & PAINT ALL PORCH & BALCONY CEILINGS.

PREP & PAINT STEEL DOORS

**GENERAL NOTES** 

PREP & PAINT ALL STUCCO, REPAIR ALL CRACKS. SP-1, SP-2, OR SP-3 VERIFY PREP & PAINT ALL RAILINGS & HANDRAILS.

CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS

2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE

3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT

REMOVE SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1.
REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, POROVIDE NEW SEALANT EJ-1 OR SL-1 VERIFY.
PREP & PAINT ALL FASCIA & SOFFIT.


9. INSPECT ROOF TILES & REPLACE BROKEN / MISSING TILES
10. REMOVE SEALANT AT ALL SIDE-WALL ROOF FLASHING LOCATIONS, PROVIDE NEW SEALANT SL-2





# OCEAN FRONT BUILDING FACADE PROJECT











**WEST ELEVATION** 



EAST ELEVATION















DETAIL N.T.S.

#### SCOPE OUTLINE (OLEANDER BUILDING)

- . PREP & PAINT ALL STUCCO. REPAIR ALL CRACKS, SP-1, SP-2 OR SR-1 VERIFY
- INSPECT TILE ROOF, REPLACE ANY BROKEN TILES.
  REMOVE SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1.
  REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, PROVIDE NEW SEALANT EJ-1 OR SL-1 VERIFY
- PREP & PAINT ALL FASCIA & SOFFIT / OUTLOOKERS.
- 6. PREP & PAINT ALL PASCIA & SOFFIT / OU
  6. PREP & PAINT ALL BALCONY CEILINGS.
  7. PREP & PAINT DOORS STEEL DOORS.
  8. PREP & STAIN ENTRY DOORS.
  9. PAINT ALL RAILINGS & HANDRAILS

#### **GENERAL NOTES**

- 1. CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS
- 2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE

3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT

# OLEANDER BUILDING FACADE PROJECT



2519	11-12-25





SOUTHEAST ELEVATION



SOUTHEAST ELEVATION




- PREP & PAINT ALL CMU WALLS
   REPAIR ROTTEN WINDOW SILLS & ANY ROTTEN TRIM. USE ABATRON WOOD EPOX AND OR ABATRON LIQUIDWOOD. SAND FOR SEAMLESS TRANSITION. PRIME FOR NEW PAINT.
   REMOVE SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1
   REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, PROVIDE NEW SEALANT EJ-1 OR SL-1 VERIFY
   PREP & PAINT FASCIA
   PREP & PAINT DOORS

#### **GENERAL NOTES**

- 1. CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS
- 2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE
- 3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT




NORTHEAST ELEVATION



# MAINTENANCE & FITNESS BUILDING

FACADE PROJECT

















DETAIL N.T.S.



SOUTHEAST ELEVATION



SCOPE OUTLINE (THE COTTAGE)

- PREP & PAINT ALL STUCCO
   PREP & PAINT ALL COLUMNS / RAILING
- PREP & PAINT PORCH CEILING
- 4. REPAIR ROTTEN WINDOW SILLS & ANY ROTTEN TRIM. USE ABATRON WOOD EPOX AND OR ABATRON LIQUIDWOOD. SAND FOR SEAMLESS TRANSITION. PRIME FOR NEW PAINT.
- 5. REMOVE SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1 6. REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, PROVIDE NEW SEALANT EJ-1 OR SL-1 VERIFY
  7. PREP & PAINT FASCIA & SOFFIT
  8. PREP & PAINT DOORS

### **GENERAL NOTES**

-PAINT STUCCO BASE & RISERS AT STAIR. P-1

- 1. CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS
- 2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE
- 3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT

### NORTHEAST ELEVATION

THE COTTAGE FACADE PROJECT


201 ARNOLD ROAD

2519	11-12-25
T 1	
L L I	





### NORTHWEST ELEVATION



NORTHEAST ELEVATION



SOUTHEAST ELEVATION



DETAIL

#### SCOPE OUTLINE (OGLETHORPE HOUSE)

- PREP & PAINT STUCCO. REPAIR ALL CRACKS, SP-1, SP-2 OR SR-1 VERIFY
   PREP & PAINT ALL DOORS
   PREP & PAINT ALL WOOD TRIM
   PREP & PAINT PORCH CEILINGS

- 5. REMOVE SEALANT AT ALL WINDOWS & DOORS, RESEAL
  6. REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, RESEAL
  7. PREP & PAINT FASCIA & SOFFIT

#### **GENERAL NOTES**

- 1. CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS
- 2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE
- 3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT

# OGLETHORPE HOUSE FACADE PROJECT




2519	11-12-25
T 1	


N.T.S.



NEW PAINT AT WOOD LATTICE — PANEL,



### NORTHEAST ELEVATION



SHUTTERS REMOVED BY—OTHERS

### NORTHWEST ELEVATION

#### **GENERAL NOTES**

- 1. CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS
- 2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE
- 3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT




— REPAIR WOOD WINDOW SILL, AS NEEDED - AT NORTHWEST ELEVATION





DETAIL G1 N.T.S.



#### SCOPE OUTLINE (WEDDING COTTAGE)

NEEDED

- REMOVE VEGETATION ON BUILDING WALLS, PREP BRICK & TABBY FOR PAINT
   PREP & PAINT HARDIE PANEL SIDING
- 3. PREP & REPAINT ROTTEN WINDOW SILLS & ROTTEN TRIM. USE ABATRON WOOD EPOX AND OR ABATRON LIQUIDWOOD. SAND FOR SEAMLESS TRANSITION. PRIME FOR NEW PAINT.
- 4. PREP / REPAIR STEEL LINTELS & PAINT
- 5. INSPECT AND REPAIR / REPOINT ANY DEGRADED MORTAR JOINTS
  6. REMOVE SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1
  7. REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, PROVIDE NEW SEALANT EJ-1
- OR SL-1 VERIFY
- 8. PREP & PAINT ALL FASCIA & SOFFIT 9. PREP & PAINT PORCH CEILINGS
- 10. PREP & PAINT DOORS

## WEDDING COTTAGE FACADE PROJECT




ST. SIMONS ISLAND, GEORGIA

2519 11-12-25 G1

**USSERY RULE MORELAN** ARCHITECTS, P.C. 1804-A FREDERICA ROAD ST. SIMONS ISLAND, GA 31522 (912) 638-6688 WWW.URarch.com ARCHITECTURE — INTERIOR DESIGN — LAND PLANNING



SOUTHEAST ELEVATION



SOUTHWEST ELEVATION





N.T.S.

NORTHEAST ELEVATION

#### SCOPE OUTLINE (WYNN COTTAGE)


- REMOVE VEGETATION ON BUILDING WALLS, PREP BRICK & TABBY FOR PAINT
   PREP & REPAINT ROTTEN WINDOW SILLS & ROTTEN TRIM. USE ABATRON WOOD EPOX AND OR ABATRON LIQUIDWOOD. SAND FOR SEAMLESS TRANSITION. PRIME FOR NEW PAINT.
- REMOVE SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1
   REMOVE SEALANT AT ALL MATERIAL JUNCTIONS, PROVIDE NEW SEALANT EJ-1
- OR SL-1 VERIFY
  5. PREP & PAINT ALL FASCIA & SOFFIT
- PREP & PAINT ALL FASCIA & SOFF
   PREP & PAINT PORCH CEILINGS
   PREP & PAINT DOORS

#### GENERAL NOTES

- 1. CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS
- 2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE
- 3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT

WYNN COTTAGE FACADE PROJECT





INSPECT ROOF FOR BROKEN OR -LOOSE TILES, REPLACE TILES AS NEEDED

REPLACE EXPANSION JOINT / SEALANT AT JOINT BETWEEN

WALL & FLOOR AT PORCHES

SOUTHEAST ELEVATION



NORTHWEST ELEVATION



REMOVED DAMAGED GUTTER,-REPLACE - MATCH EXISTING

REMOVED DAMAGED GUTTER,

REPLACE - MATCH EXISTING



#### **SCOPE OUTLINE** (TABBY HOUSE)

- PREP & PAINT ALUMINUM TRIM COIL AT FASCIA. PREP &PAINT STUCCO, REPAIR ALL CRACKS, SP-1, SP-2 OR SR-1 VERIFY
- PREP & PAINT ALL RAILING & HANDRAILS.
  PREP & PAINT COLUMNS.
  REMOVE EXISTING SEALANT AT ALL WINDOWS & DOORS, PROVIDE NEW SEALANT SL-1
- REPLACE DAMAGED GUTTERS.
   INSPECT ROOF TILES & REPLACE BROKEN TILES.
   PREP & PAINT PORCH CEILINGS.
   PREP & PAINT DOORS.

#### **GENERAL NOTES**

- 1. CONTRACTOR TO VISIT ALL BUILDINGS AND VERIFY ALL CONDITIONS
- 2. SEE SHEET G1 FOR SPECIFICATIONS AND PAINT SCHEDULE
- 3. SEE SHEET AS1 FOR BUILDING LOCATION & BUILDING FOOTPRINT





SOUTHWEST ELEVATION

# TABBY HOUSE FACADE PROJECT

